

ELECTRICAL TROUBLESHOOTING GUIDE FOR EVANS TEMPCON DUAL ZONE HEATER – A/C SYSTEMS

PROBLEM	POSSIBLE CAUSES	REMEDY
<p>1. A/C clutch does not operate; blower operates as it should.</p>	<ul style="list-style-type: none"> • Faulty rotary mode selector switch. • Clutch circuit wires have fallen off of clutch terminals, thermostat, or pressure switch. • Faulty A/C thermostat. • Faulty A/C pressure switch (make certain adequate refrigerant is contained in system) • Faulty A/C clutch. • Faulty chassis circuitry (GM and Ford) 	<ul style="list-style-type: none"> • Check for switch continuity; replace if necessary. • Re-install clutch circuit wires as required. • Jump across thermostat terminals. If clutch engages, replace thermostat. • Ensure switch is tight on fitting. • Jump across switch terminals (A/C thermostat and “comp” terminals for trinary switch). If clutch engages, replace switch • With engine OFF, apply 12V+ supply directly to clutch terminals and listen for clutch engagement. Replace clutch if there is no engagement. • Referring to Chassis A/C schematic, if voltage is read at point “A” when A/C switch is depressed and clutch engages when 12V+ power is applied directly to clutch terminal, problem is originating in chassis wiring. Refer to Chassis Manufacturer’s service manual.
<p>2. HVAC accessory fuse blows when rotary mode selector switch is in any position except OFF, VENT, and FLOOR.</p>	<ul style="list-style-type: none"> • Short circuit in clutch circuit wiring • Short circuit in clutch. 	<ul style="list-style-type: none"> • Inspect all associated wiring (see system schematic) from control panel to clutch. • With engine OFF apply an 8 amp fused 12V+ power supply directly to clutch terminals. If fuse blows, replace clutch.
<p>3. Blowers do not operate at any speed.</p>	<ul style="list-style-type: none"> • Mode Selector switch in OFF position. • Main harness leads (power or ground) disconnected at vehicle power supply or ground source. 	<ul style="list-style-type: none"> • Designed response. • Check connections from HVAC fuse panel to vehicle power and ground sources.

NOTE: FOLLOW DIAGNOSIS PROCEDURE IN “REMEDY” COLUMN IN THE ORDER LISTED.

**ELECTRICAL TROUBLESHOOTING GUIDE
FOR EVANS TEMPCON DUAL ZONE HEATER – A/C SYSTEMS**

PROBLEM	POSSIBLE CAUSES	REMEDY
3. Blowers do not operate at any speed. (Continued)	<ul style="list-style-type: none"> • Loose terminal(s) in fuse block relay cavities. • Connector disconnected from mode selector switch at main control panel. • Faulty mode selector switch. • Improperly installed connectors. 	<ul style="list-style-type: none"> • Check terminals at Relays B and F to ensure they are locked into their cavities. • Install connector. • With vehicle ignition switch in the ON position, rotate the mode selector switch to any position except OFF. Using a voltmeter, check for voltage at mode switch, circuit 012 red (see schematic). If no voltage is read, replace mode selector switch. • Inspect harness connections between main harness, fuse panel harness (split harness systems only), and base unit. Ensure terminals are seated in connector and that connectors are locked together.
4. No blower speed on driver side.	<ul style="list-style-type: none"> • Blown fuse in HVAC fuse panel. • Improperly installed connectors at blower switch or base unit connector. 	<ul style="list-style-type: none"> • Check continuity of fuse, position 6. Replace if blown. • Check connector at main control panel blower switch and 8 pin connector at base unit. Check wire blocking in connector.
5. No blower speed on passenger side.	<ul style="list-style-type: none"> • Blown fuse in HVAC fuse panel. • Improperly installed connector to passenger blower switch, passenger resistor on base unit or passenger control harness to main harness. 	<ul style="list-style-type: none"> • Check continuity of fuse, position 5. Replace if blown. • Check connector at passenger control panel blower switch, connector on resistor and 6 pin junction between passenger harness and main harness.
6. Driver side blower does not operate on HIGH speed.	<ul style="list-style-type: none"> • Improperly installed connectors at blower switch or base unit connector. 	<ul style="list-style-type: none"> • Check connector at main control panel blower switch and 8 pin connector at base unit. Check wire blocking in connector.

NOTE: FOLLOW DIAGNOSIS PROCEDURE IN "REMEDY" COLUMN IN THE ORDER LISTED.

ELECTRICAL TROUBLESHOOTING GUIDE FOR EVANS TEMPCON DUAL ZONE HEATER – A/C SYSTEMS

PROBLEM	POSSIBLE CAUSES	REMEDY
6. Driver side blower does not operate on HIGH speed. (continued)	<ul style="list-style-type: none"> • Improperly installed connectors between main harness and fuse panel harness (split harness systems only). • Terminals loose at relay J in fuse panel. • Improperly installed connector at base unit. 	<ul style="list-style-type: none"> • Inspect harness connections between the main harness and the fuse panel harness. Ensure terminals are seated in the connector halves and that connectors are locked together. • Pull relay J from fuse panel and check to see if terminals are properly seated in cavities. Repair if necessary. • Check connection to base unit. Check wire blocking in connector.
7. Passenger blower does not operate on HIGH speed.	<ul style="list-style-type: none"> • Improperly installed connectors at blower switch; main harness to passenger harness, fuse panel harness or base unit harness and resistor. • Improperly seated terminals at relays E or G in HVAC fuse panel. 	<ul style="list-style-type: none"> • Check harness connections. Ensure pins are seated in connectors and connectors are locked together. • Pull relays and check to ensure terminals are properly seated in correct cavities.
8. Driver blower comes on/stays on HIGH speed when Mode selector is in any position except OFF.	<ul style="list-style-type: none"> • Circuits 004 (red) and 013 (red w/black trace) reversed, most likely at base unit connector. 	<ul style="list-style-type: none"> • Check cavity positions of wires (see electrical schematic).
9. Passenger blower switch controls driver side air speed when driver control is in OFF position.	<ul style="list-style-type: none"> • Circuits in wrong cavities at relay H in HVAC fuse panel; circuit 011 (green) switched with 013 (red). 	<ul style="list-style-type: none"> • Check cavity positions of wires. Circuit 011 should be in cavity 30, 013 should be in cavity 87 (see schematic).
10. Driver temperature dial does not control passenger side discharged air temperature in DRIVER OVERRIDE mode.	<ul style="list-style-type: none"> • Loose wire or defective relay at Relay D in HVAC fuse panel. 	<ul style="list-style-type: none"> • Pull relay and check to ensure terminals are properly seated in correct cavities. Test relay for proper function; replace if defective.
11. Driver blower control does not control passenger side discharged air speed in DRIVER OVERRIDE mode.	<ul style="list-style-type: none"> • Override switch disconnected. • Open circuit (018 Purple) between override switch and relay H in HVAC fuse panel 	<ul style="list-style-type: none"> • Check connection to override switch. • Check continuity of circuit (see schematic). Check terminals at relay to ensure they are locked into cavities.

NOTE: FOLLOW DIAGNOSIS PROCEDURE IN "REMEDY" COLUMN IN THE ORDER LISTED.